

MATERIAL SAFETY DATA SHEET

PRODUCT INFORMATION

Product Name: WC8329
General/Generic Name: SCALE AND CORROSION CONTROL
COOLING WATER TREATMENT

TDG Hazard Classification: NOT REGULATED
WHMIS Classification: NOT REGULATED

Vendor Name & Address: HOOD CHEMICAL
295 ALLIANCE ROAD #14
MILTON ON L9T 4W8

HAZARDOUS INGREDIENTS

Ingredient	%W/W	TLV	CAS. NO.	LD50	LC50
NOT WHMIS REGULATED					

PHYSICA DATA

Physical State: LIQUID
Appearance & Odour: CLEAR YELLOW LIQUID, NO ODOUR
Odour Threshold: ND
Specific Gravity: 1.04
Vapour Pressure: 28MM
Vapour Density: 2GR/LITRE
pH: 11.4
Evaporation Rate: SAME AS WATER
Initial Boiling Point: 100°C
Water Solubility: COMPLETELY DISPERSABLE
Freezing Point: 0°C

FIRE OR EXPLOSION HAZARD

Flash Point: NONE
Flammable Limits: NONE
Auto-Ignition Temp: NONE
Extinguishing Media: NONE
Special Firefighting Procedure: CONTAINER MAY EXPLODE IF HEATED
Explosion Data: NONE APPLICABLE
Hazardous Combustion Product: NONE

REACTIVITY DATA

Stability: STABLE
Incompatibility: NONE THAT CAUSE HAZARDS
Hazardous Decomposition Products: NONE
Conditions To Avoid: NONE THAT CAUSE HAZARDS

 TOXICOLOGICAL PROPERTY

Threshold Limit Value:	ND
Effects of Acute Exposure:	DRY SKIN
Skin Contact:	MAY CAUSE DRY SKIN
Skin Absorption:	NONE
Eye Contact:	TRANSIENT IRRITATION
Inhalation:	IRRITATION OF MUCOUS MEMBRANES
Ingestion:	G.I. TRACT IRRITATION
Effect of Chronic Exposure:	NONE
Irritancy of Product:	MILD IRRITANT TO SKIN AND EYES
Carcinogenicity:	ND
Sensitization to Material:	NONE
Reproduction Toxicity:	ND
Teratogenicity:	ND
Mutagenicity:	ND

 PREVENTATIVE MEASURES

Protective Equipment To be Used:	USUALLY NONE REQUIRED
Respiratory Protection:	NONE REQUIRED
Ventilation:	NORMAL AIR FLOW
Protective Gloves:	NONE
Eye Protection:	SAFETY GLASSES
Other Protective Measures:	NONE

SPILL OR LEAK PROCEDURES:

Steps To Be Taken In Case Material Is Released or Spilled:
 CONTAIN SPILL, ABSORB ONTO INERT MATERIALS

Waste Disposal Information:

DISPOSE OF IN ACCORDANCE WITH ALL LOCAL, PROVINCIAL AND
 FEDERAL GOVERNMENT REGULATIONS

 FIRST AID MEASURES

Skin Contact:	WASH WITH SOAP AND WATER
Eye Contact:	RINSE EYES WITH PLENTY OF WATER. SEEK MEDICAL ATTENTION IF IRRITATION PERSISTS.
Inhalation:	REMOVE TO FRESH AIR
Ingestion:	DRINK PLENTY OF WATER OR MILK

 PREPARATION INFORMATION

Date Revised:	January 2016		
	NA	Not Applicable	
Prepared by:	LAB PERSONNEL	ND	No Data Available
Phone:	905-876-0707	NE	None Established
		NR	Not Regulated